CESA: 07 Number of schools reported for CESA 07: 133

Which best describes the location of your school building?

0	0.00%	Large Central City (Population greater than 400,000 and density greater than 6,000.)
64	48.12%	Mid-Size Central City (Population less than 400,000 and density less than 6,000.)
0	0.00%	Urban Fringe of Large City (Defined as urban by the Census Bureau.)
18	13.53%	Urban Fringe of Mid-Size City (Defined as urban by the Census Bureau.)
10	7.52%	Large Town (Population greater than or equal to 25,000.)
18	13.53%	Small Town (Population less than 25,000 and greater than or equal to 2,500.)

## 23 **17.29%** Rural (Population less than 2,500 and coded rural by the Census Bureau.)

## PHYSICAL STRUCTURE AND MECHANICAL FEATURES

4. When was the school originally constructed	ted?	construct	originally	school	was the	When	4.
---	------	-----------	------------	--------	---------	------	----

Pre-1900	1	0.75%	1930-1939	14	10.53%	1970-1979	19	14.29%
1900-1909	0	0.00%	1940-1949	0	0.00%	1980-1989	3	2.26%
1910-1919	7	5.26%	1950-1959	27	20.30%	1990-1999	15	11.28%
1920-1929	11	8.27%	1960-1969	36	27.07%			

5. In your opinion, is this school building overcrowded?

Yes 28 **21.05%** No 105 **78.95%** 

6. If the original building has been renovated or had additions, when was the most recent, MAJOR renovation or addition?

No Renovation	36	27.07%	1940-1949	0	0.00%	1970-1979	5	3.76%
Before 1930	2	1.50%	1950-1959	4	3.01%	1980-1989	12	9.02%
1930-1939	0	0.00%	1960-1969	4	3.01%	1990-1999	70	52.63%

7. How many total square feet does the original building have?

Minimum: 2,264 Maximum: 283,406 Median: 55,000 Average: 71,905

8. If the building has been renovated or added on to, how many total square feet exist now?

Minimum: 11,761 Maximum: 424,195 Median: 65,000 Average: 95,908

9. How many portable classrooms were in use during the 1998-99 school year?

Number of schools reporting the use of portable classrooms: 5

Minimum: 2 Maximum: 3 Median: 2 Average: 2

10. Does the school accommodate any of its students in instructional facilities located OFF-SITE?

Yes 6 **4.51%** No 127 **95.49%** 

11. How many of this school's FTE students are located in OFF-SITE facilities?

Number of schools reporting OFF-SITE facilities: 6

Minimum: 8 Maximum: 60 Median: 12 Average: 21

CESA: 07 Number of schools reported for CESA 07: 133

## Definitions for questions #12 and #15:

**Excellent:** New or easily restorable to "like new" only minimal routine maintenance.

**Good:** Only routine maintenance or minor repair required.

Adequate: Some preventive maintenance and/or corrective repair required.

Fair: Fails to meet code and functional requirement in some cases; extensive repair.

Poor: Consistent substandard performance; major corrective repair or overhaul.

Replace: Non-operational or significantly substandard performance. Replacement

NA: Not Applicable

12. What is the overall condition of the original buildings and the permanent additions?

	Excellent	Good	Adequate	Fair	Poor	Replace	NA
Original Buildings:	30	68	25	6	1	3	0
	<b>22.56%</b>	<b>51.13%</b>	<b>18.80%</b>	<b>4.51%</b>	<b>0.75%</b>	<b>2.26%</b>	<b>0.00%</b>
Permanent Additions:	45	36	12	2	2	0	36
	<b>33.83%</b>	<b>27.07%</b>	<b>9.02%</b>	<b>1.50%</b>	<b>1.50%</b>	<b>0.00%</b>	<b>27.07%</b>

13. What would be the total cost of all repairs/renovations/modernizations required to put this school's ON-SITE buildings in good overall condition?

Number of schools reporting cost for repairs/renovations/modernizations:

37

CESA Total Costs = \$118,764,400

Minimum: \$20,000 Maximum: \$18,500,000 Median: \$500,000 Average: \$3,209,849

14. On which of the sources listed below is this estimate based? Choose all that apply.

100 **53.48%** Does not apply--already in good (or better) overall condition.

17 **9.09%** Facilities inspection/assessment performed within the last three years by licensed professionals.

15 **8.02%** Repair/renovation/modernization work already being performed/contracted for.

17 9.09% Capital improvement/facilities master plan or schedule.

23 12.30% My best professional judgement.

15 **8.02%** Opinions of others.

15. Overall, what is the physical condition of each of the building features listed below for this school's ON-SITE buildings?

	Excellent	Good	Adequate	Fair	Poor	Replace
Roofs:	34	63	30	3	3	0
	<b>25.56%</b>	<b>47.37%</b>	<b>22.56%</b>	<b>2.26%</b>	<b>2.26%</b>	<b>0.00%</b>
Framing, floors, foundations:	42	71	17	3	0	0
	<b>31.58%</b>	<b>53.38%</b>	<b>12.78%</b>	<b>2.26%</b>	<b>0.00%</b>	<b>0.00%</b>
Exterior walls, finishes, windows, doors:	41	65	21	5	1	0
	<b>30.83%</b>	<b>48.87%</b>	<b>15.79%</b>	<b>3.76%</b>	<b>0.75%</b>	<b>0.00%</b>
Interior finishes, trims:	35	71	21	5	1	0
	<b>26.32%</b>	<b>53.38%</b>	<b>15.79%</b>	<b>3.76%</b>	<b>0.75%</b>	<b>0.00%</b>
Plumbing:	29	74	21	3	5	1
	<b>21.80%</b>	<b>55.64%</b>	<b>15.79%</b>	<b>2.26%</b>	<b>3.76%</b>	<b>0.75%</b>
Heating ventilation, air conditioning:	32	65	25	6	4	1
	<b>24.06%</b>	<b>48.87%</b>	<b>18.80%</b>	<b>4.51%</b>	3.01%	<b>0.75%</b>
Electrical power:	38	62	22	4	7	0
	<b>28.57</b> %	<b>46.62</b> %	1 <b>6.54%</b>	3.01%	<b>5.26%</b>	<b>0.00%</b>
Electrical lighting:	39	72	20	1	1	0
	<b>29.32%</b>	<b>54.14%</b>	<b>15.04%</b>	<b>0.75%</b>	<b>0.75%</b>	<b>0.00%</b>
Life safety requirements (e.g., emergency lighting and warning systems, exit signs):	40	78	11	4	0	0
	<b>30.08%</b>	<b>58.65%</b>	<b>8.27%</b>	3.01%	<b>0.00%</b>	<b>0.00%</b>

Number of schools reported for CESA 07: 133 CESA: 07

16. How adequate is your current maintenance budget for keeping your buildings in good overall condition?

	Very Adequate:	7	5.26%				Somewh	at Adequate:	15	11.28%	
	Adeguate:	104	78.20%				Not ad	lequate at all:	7	5.26%	
17.	How satisfactory or unsa	tisfacto	ry is each (	of the	following e	nviron	mental facto	ors in this scho	ol's ON	I-SITE build	ings?
			Very Sa	tisfac	tory	Satis	factory	Unsatisfa	actory	Very Ur	nsatisfactory
	Li	ghting:	48	36.0	9%	83	62.41%	2	1.50%	0	0.00%
	Н	eating:	42	31.5	8%	87	65.41%	3	2.26%	0	0.75%
	Vent	ilation:	38	28.5	57%	81	60.90%	13	9.77%	1	0.75%
	Indoor air d	quality:	37	27.8	2%	89	66.92%	7	5.26%	0	0.00%
	Acoustics for noise of	control:	33	24.8	31%	89	66.92%	10	7.52%	1	0.75%
	Flexibility of instructional	space:	27	20.3	80%	83	62.41%	21 <b>1</b>	5.79%	2	1.50%
	Energy efficiency/conser	vation:	27	20.3	80%	89	66.92%	15 <b>1</b>	1.28%	2	1.50%
	Physical security of but	ildings:	37	27.8	32%	78	58.65%	13	9.77%	5	3.76%
	Exterior	noise:	47	35.3	34%	82	61.65%	3	2.26%	1	0.75%
18.	How many instructional of Total number o								eptemb	er, 1998:	4,543
	Minimum: 1		Maximur	n:	116		Median:	28		Average:	34
19.	Does the school building	have C	ENTRAL &	air co	nditioning (d	ools a	ll interior sp	ace)?			
	Yes 44 <b>33.08%</b>		No	89	66.92%		•	,			
20	Does this school have ai	ir oondit	ionina in in	otruo	tional alass	oomo	computer l	aha and/arth	o libron	,o	
20.			-			ooms,	computer is	aus, anu/or un	э ны агу	· <del>?</del>	
			structional		STOOMS.						
			omputer la: e library.	DS.							
	31 <b>31.03</b> /6 F	65, III UI	e iibi ai y.								
21.	How many instructional of	classroc	ms have a	air co	nditioning?						
	Minimum: 1		Maximur	n:	21		Median:	5		Average:	6
22.	Does this school have a	separat	e room for	a lib	rary/resourc	e/med	lia center?				
	Yes 129 <b>96.99%</b>		No	4	3.01%						
23.	How does the size of you in your building?	ur schoo	ol's library/	resou	ırce/media d	enter	compare wi	th the size of a	a typicai	l classroom	
	Smaller: 2 <b>1.54</b>	<b>%</b>	About t	he sa	ame size:	7	5.38%	Larger:	121	93.08%	
24.	How many classrooms v	vould fit	in the spa	ce us	ed for your	library	/resource/m	edia center?			
	Minimum: .75		Maximur		3		Median:	3		Average:	3
25	If we have a library for a						<b>- 1- 6</b>		0	-	
<b>2</b> 5.	If you have a library/reso Yes 116 89.23%		eaia centei No	r, is it 14	10.77%	a iicen	sea, protess	sionai Iidrarian	<i>?</i>		
26.	What percent time is you Number of sch										116
	Minimum: 10%		Maximur	n: '	100%		Median:	100%		Average:	75.8%

Median: 100%

Average: 75.8%

Agree with statement:

44

50.00%

Strongly disagree with statement:

9.09%

CESA: 07 Number of schools reported for CESA 07: 133 27. Does this school have a separate room for a parent/family center? Yes 30 22.56% 103 77.44% No 28. How does the size of your school's parent/family center compare with the size of a typical classroom in your building? 10 33.33% About the same size: Smaller: 17 **56.67%** Larger: 3 10.00% 29. How many classrooms would fit in the space used for the parent/family center? Minimum: .33 Maximum: 2 Median: Average: 1 B. SCHOOL SAFETY 30. Does your school have a "Locked Door" policy (doors can only be opened from the inside)? 110 82.71% No 23 17.29% 31. Does your school have a "Check-In" policy for school visitors? Yes 128 96.24% No 5 3.76% 32. Does your school have an established emergency response plan for dealing with school safety issues? Yes 133 **100.00%** No 0 0.00% 33. Does your school have on-site security provided by police officers or private security guards? Yes 17 12.78% No 116 87.22% 34. Does your school have parent or other community volunteers to assist in monitoring the school? Yes 43 32.33% No 90 67.67% 35. Does your school have metal detectors? Yes 0 0.00% No 133 100.00% 36. Does your school have surveillance cameras located within the school building or on school grounds? Yes 5.26% No 126 94.74% C. EDUCATIONAL APPROPRIATENESS AND SUITABILITY **ELEMENTARY SCHOOLS ONLY Number of Elementary Schools Reported:** 81 Educational Appropriateness: 38. Size of instructional classrooms are large enough to allow for alternative room arrangements to facilitate curricular objectives. Strongly agree with statement: 33 37.50% Disagree with statement: 9 10.23% Agree with statement: 45 51.14% Strongly disagree with statement: 1 1.14% 39. Pre-kindergarten and Kindergarten space accommodates developmental range and needs of young children by providing a minimum of 35 square feet per occupant. Strongly agree with statement: 30 34.09% Disagree with statement: 6 6.82%

Agree with statement:

43

47.78%

Strongly disagree with statement:

3

3.33%

**CESA: 07** Number of schools reported for CESA 07: 133 Number of Elementary Schools reported for CESA 07: 81 40. Adequate space is available for small work group instruction (less than 15 students). Strongly agree with statement: 25 28.41% Disagree with statement: 17 19.32% Agree with statement: 44 50.00% 2 Strongly disagree with statement: 2.27% 41. Adequate space is available to allow instructional classrooms to maintain a class size of less than 30 students. Strongly agree with statement: 38 43.18% Disagree with statement: 4.55% 44 50.00% 2 Agree with statement: Strongly disagree with statement: 2.27% 42. Adequate space is available for large work group instruction (more than 30 students). Strongly agree with statement: 25 28.41% Disagree with statement: 21 23.86% Agree with statement: 36 40.91% Strongly disagree with statement: 6 6.82% 43. Equipment and furniture (such as shelving units, tables, and chairs) are the appropriate size for the building's student population. Strongly agree with statement: 39 44.32% Disagree with statement: 2 2.27% Agree with statement: 46 52.27% Strongly disagree with statement: 1 1.14% **Building Suitability for Education:** 44. Buildings materials, color schemes, and decor provide impetus to learning. Strongly agree with statement: 30 34.09% 2 Disagree with statement: 2.27% Agree with statement: 54 61.36% Strongly disagree with statement: 2 2.27% 45. Drinking fountain and restroom facilities are an appropriate height and size for the school building population and conveniently located. Strongly agree with statement: 36 40.91% Disagree with statement: 7 7.95% Agree with statement: 43 48.86% Strongly disagree with statement: 2 2.27% 46. Student services areas (e.g., counselor and medical) ensure privacy and are of sufficient size. Strongly agree with statement: 30 34.09% Disagree with statement: 11 12.50% Agree with statement: 41 46.59% Strongly disagree with statement: 6 6.82% 47. Building is accessible to students with disabilities. Strongly agree with statement: 39 44.32% 6 Disagree with statement: 6.82% Agree with statement: 42 47.73% Strongly disagree with statement: 1 1.14% 48. Space is available and appropriate for extended day learning opportunities, including before and after school day care. Strongly agree with statement: 23 26.14% Disagree with statement: 20 22.73% Agree with statement: 42 47.73% Strongly disagree with statement: 3 3.41% School Site Suitability: 49. Site is large enough to meet educational needs and is accessible. Strongly agree with statement: 35 38.89% Disagree with statement: 9 10.00%

81

CESA: 07 Number of	f school	s reported for CES	A 07: 133  Number of Elementary Schools report	ted for	CESA 07:
50. Site has a safe outdoor space	where c	hildren can engage ir	n a variety of games, sports, and motor	activitie	9S.
Strongly agree with statement:	36	40.91%	Disagree with statement:	8	9.09%
Agree with statement:	44	50.00%	Strongly disagree with statement:	0	0.00%
51. Student loading areas are seg	regated :	from other vehicular i	traffic and pedestrian walkways		
Strongly agree with statement:	19	21.59%	Disagree with statement:	22	25.00%
Agree with statement:	41	46.59%	Strongly disagree with statement:	6	6.82%
Playground Site and Equipment	Suitahil	litv:			
52. Playground size is appropriate		-			
		39.77%	Diagram with statement	10	11.36%
Strongly agree with statement:  Agree with statement:	35 41		Disagree with statement:	10	11.36% 2.27%
Agree with statement.	41	46.59%	Strongly disagree with statement:	2	2.21%
53. Playgrounds are separated fro	m street	s and parking areas	with fencing or other permanent materia	ıl.	
Strongly agree with statement:	28	31.82%	Disagree with statement:	15	17.05%
Agree with statement:	40	45.45%	Strongly disagree with statement:	5	5.68%
54. Playgrounds are well equipped	d and ap	propriate for age leve	els.		
Strongly agree with statement:	28	31.82%	Disagree with statement:	9	10.23%
Agree with statement:	47	53.41%	Strongly disagree with statement:	4	4.55%
55. Playground equipment is acce	ssible to	students with disabil	lities.		
Strongly agree with statement:	26	29.55%	Disagree with statement:	14	15.91%
Agree with statement:	42	47.73%	Strongly disagree with statement:	6	6.82%
56. Playground equipment is free	of sharp	edaes, of sound con-	struction, and in good condition.		
Strongly agree with statement:	33	37.50%	Disagree with statement:	5	5.68%
Agree with statement:	48	54.55%	Strongly disagree with statement:	2	2.27%
MIDDLE, JUNIOR HIGH, AND Educational Appropriateness:	HIGH S	SCHOOLS ONLY	Number of Secondary Schools F	Report	<b>ed:</b> 52
57. Size of instructional classroom objectives.	s are lar	rge enough to allow fo	or alternative room arrangements to fac	ilitate c	curricular
Strongly agree with statement:	14	24.56%	Disagree with statement:	11	19.30%
Agree with statement:	32	56.14%	Strongly disagree with statement:	0	0.00%
58. Size and design of special lear compatible with instructional n		eas (science labs, art,	technology education, music and speci	ial edud	cation) is
Strongly agree with statement:	16	28.57%	Disagree with statement:	15	26.79%
Agree with statement:	21	37.50%	Strongly disagree with statement:	4	7.14%
59. Adequate space is available fo	or small v	vork group instruction	n (less than 15 students).		
Strongly agree with statement:	14	25.00%	Disagree with statement:	8	14.29%
Agree with statement:	33	58.93%	Strongly disagree with statement:	1	1.79%

CESA: 07	Number of school	ols reported	for CESA 07: 133 Number of Secondary Schools repo	rted for	CESA 07: 52
60. Adequate space	is available to allow	instructional c	classrooms to maintain a class size of less than	30 stud	ents.
Strongly agree wi	th statement: 20	35.71%	Disagree with statement:	9	16.07%
Agree wi	ith statement: 26	46.43%	Strongly disagree with statement:	1	1.79%
61. Adequate space	is available for large	work group ir	nstruction (more than 30 students).		
Strongly agree wi	th statement: 11	19.64%	Disagree with statement:	17	30.36%
Agree wi	ith statement: 25	44.64%	Strongly disagree with statement:	3	5.36%
Building Suitability	for Education:				
62. Buildings materia	als, color schemes, a	and decor prov	vide impetus to learning.		
Strongly agree wi	ith statement: 18	32.14%	Disagree with statement:	6	10.71%
Agree wi	ith statement: 30	53.57%	Strongly disagree with statement:	2	3.57%
63. Drinking fountain conveniently loca		es are an app	ropriate height and size for the school building ந	oopulatio	on and
Strongly agree wi	ith statement: 14	25.00%	Disagree with statement:	2	3.57%
Agree wi	ith statement: 40	71.43%	Strongly disagree with statement:	0	0.00%
64. Student services	areas (e.g., counse	lor and medic	al) ensure privacy and are of sufficient size.		
Strongly agree wi	ith statement: 11	19.64%	Disagree with statement:	8	14.29%
Agree w	ith statement: 32	57.14%	Strongly disagree with statement:	5	8.93%
65. Building is acces	sible to students with	h disabilities.			
Strongly agree wi	ith statement: 27	48.21%	Disagree with statement:	1	1.79%
Agree w	ith statement: 27	48.21%	Strongly disagree with statement:	1	1.79%
66. Space is availab	le and appropriate fo	or extended da	ay learning opportunities, including before and a	fter sch	ool day care.
Strongly agree wi	ith statement: 8	14.29%	Disagree with statement:	12	21.43%
Agree w	ith statement: 33	58.93%	Strongly disagree with statement:	3	5.36%
School Site Suitabil	lity:				
67. Site is large eno	ugh to meet educatio	onal needs an	d is accessible.		
Strongly agree wi	ith statement: 13	23.21%	Disagree with statement:	8	14.29%
Agree w	ith statement: 32	57.14%	Strongly disagree with statement:	3	5.36%
68. Site has a safe o	utdoor space where	students can	engage in a variety of games, sports, and moto	r activiti	ies.
Strongly agree wi	ith statement: 16	28.57%	Disagree with statement:	0	0.00%
Agree w	ith statement: 38	67.86%	Strongly disagree with statement:	2	3.57%
69. Student loading	areas are segregate	d from other v	rehicular traffic and pedestrian walkways.		
Strongly agree wi		5.36%	Disagree with statement:	19	33.93%
Agree w	ith statement: 29	51.79%	Strongly disagree with statement:	5	8.93%